

# WELDING

## SYSTEM OVERVIEW

No.	Description	Name	Art No.
1.	Welding shield	SR 591	H06-4312
2.	Welding shield with air channel	SR 592	H06-4412
3.	Welding shield/ Helmet with visor	SR 584/ SR 580	H06-8310
4.	Welding shield/ Visor, EN 10 Welding shield/ Visor, EN 4/9-13	SR 574/ SR 570 SR 574/ SR 570	H06-6110 H06-6810
5.	Half mask	SR 900 S SR 900 M SR 900 L	H01-3012 H01-3112 H01-3212
6.	Remote filter holder	SR 905	T01-3002
7.	Fan unit	SR 500	H06-0112
8.	Fan unit	SR 700	H06-7010
9.	Compressed air attachment	SR 507	H03-0612
10.	Hose	SR 951	T01-3003
11.	Twin hose	SR 952	R01-3009
12.	Breathing hose for SR 592 Breathing hose for SR 574/SR 570 Breathing hose for SR 584/SR 580		R06-4401 R06-0635 R06-0810
13.	Particle filter P3 R	SR 510	H02-1312
14.	Particle filter P3 R	SR 710	H02-1512
15.	Gas filter A1 Gas filter A2 Gas filter A2AX Gas filter ABE1 Gas filter A2B2E1 Gas filter K1 Gas filter K2 Gas filter ABEK1	SR 217 SR 218 SR 298 SR 315 SR 294 SR 316 SR 295 SR 297	H02-2512 H02-2012 H02-2412 H02-3212 H02-3312 H02-4213 H02-4312 H02-5312
16.	Gas filter A2 Gas filter ABE1 Gas filter A1BE2K1	SR 518 SR 515 SR 597	H02-7012 H02-7112 H02-7212
17.	Combined filter ABEK1-Hg-P3 R	SR 299-2	H02-6512
18.	Combined filter A1BE2K1-Hg-P3 R	SR 599	H02-7312
19.	Hose	SR 360	H03-34XX
20.	Hose	SR 358	H03-30XX
21.	Hose	SR 359	H03-31XX
22.	Compressed air filter	SR 99-1	H03-2810

